
INFORMATION *from* **Headline Filters**

ATEX Certification

ATEX Directive 94/9/EC

November 2007

We have been advised by our Notified body & the DTI that our filter housings need not be certified under the ATEX Directive, as they do not have their own source of ignition.



Scott Hardiman
Works Manager



FM51967